AGENDA

Work Session

STE. GENEVIEVE BOARD OF ALDERMEN

Thursday – April 24, 2025 City Hall, 165 S. 4th St.

Immediately Following 6:00 p.m. Regular Board Meeting

CALL TO ORDER

APPROVAL OF AGENDA

BUSINESS ITEMS

- 1. Police Car Engine Replacement
- 2. Resident Basement Backup Mike James

OTHER BUSINESS

ADJOURNMENT

Any person requiring special accommodations (i.e. qualified interpreter, large print, hearing assistance) in order to attend the meeting please notify this office at 573-883-5400 no later than forty-eight hours prior to the scheduled commencement of the meeting.

Join us on the Zoom app at:

https://us02web.zoom.us/j/84811211564?pwd=VnR5QVppTEhYMWYxWGszT2xqTW1YZz09

Or by phone at (312) 626-6799 Meeting ID: 848 1121 1564 Passcode: 808225 Find the Zoom Link at www.facebook.com/stegenevievecityhall/

Posted 4/19/2025 Happy Welch

Staff Report

April 24, 2025

To: Board of Aldermen From: Happy Welch

Re: Police Vehicle Engine



Issue:

The police department had an engine lock up out of warranty and are requesting to replace the engine. This is one of the vehicles we were going to roll out of the rotation this year but funds were cut. If the engine is replaced the vehicle will replace the black explorer as the part-time officer vehicle.

There are 3 options:

Do nothing. We'll scrap it in the next budget year. Cost - \$0.00

Replace the engine through a Dodge dealership. That would include a warranty. Cost - \$9,746.78

Replace the engine with help from Alliance to install the engine at the Public Works Bldg (Street Shed). Cost - \$5,053.67 + parts.

Recommendation:

We sell it for scrap and move on. The department will have to share vehicles in the interim.



12830 Highway 21 De Soto, Missouri 63020

Phone | 636-337-7777

147		DJFGXLC		R POLLOCK 165 S 4TH STREET			DATE IN 02/27/25
. (ÖDGE	purango ss ste. Genevieve mo 63670			(IMEIN		
S IN	MILES OUT	FRSTUSE	LISC.	C:() - H:(573) 883-3999	W; ()		DIOSED
		3,444,244,244			.,,		WALTER
			Marker Marker of the Control of the				MELISSA
CUST	NE REPLACE		A	68082860AB 68297850AC 68298751AB 68093232AA 4861965AA 4893803AA 4893806AB 5184772AB	ENGINE ADHESIVE GSKT PKG GASKET GASKET SEAL SEAL SEAL FILTER GUSTONER GUSTO) 1) 1) 1) 1) 2) 1) 2) 4) 1) 6) 1	4070.00 4750.00 32.93 250.00 250.00 61.16 27.30 39.66 51.32 37.95 130.50 10.00 4070.00 5640.82 35.96 9746.78
DEHALF OF SI LESS ONNERW MEATION FROM SCLUMINGS SCLUMINGS	ENVICING DEALER, 1 HEREBY INSE SKOWN, SERVICES DESC TIME APPEARANCE OF THE WE BEEN COUNEEDED IN ARY WAY AVAILABLE FOR (1) YEAR FRO	CORE 90 days. CERTIFY THAT THE HEFORMATION CONTROL MARCH WARE PERFORMED AT NO CHANGE TO HAVE AND MARCH CONTROL TO MARCH CONTROL OF A HISTORY AND ACT OF THE CONTROL OF THE	FO HEREOR IS ACCUINATE SUPERATE OF MAN OF MA	A OF WARROUTIES: The factory software and of the werander with so acts of the Interference The Select social containers at womening of the social containers of womening of the social containers of womening of the social containers of the containers social containers of the social containers of the social containers are malantees social containers and malantees social containers are malantees social containers social cont	.00	316 . 4 . 4	CUSTOMER 4070.00 5640.82 .00 35.96
SPECTION SYM	INDESCRIPTION OF THE PRESENT	ATIVE.	ESSENACING DEALER FOR connections	with the sale of this Retrymen's.	00 00	Sub Total Tax	9746.78 616.50 10363.28

NUTECH

Engine

Part #:

DDHH

SKU:

1369796

Price:

\$4293.67 Prices and availability are subject to

change

List Price:


\$8587.34

Core:

\$760.00

Warranty:

4 Years



Intake Manifold Included

No

Cylinder Head Material

Aluminum

Piston Style

Flat

Piston Valve Reliefs

No

Yes

Assembled

Engine Oil Pump Included

Yes

Flywheel Included

No

Grade Type

Premium

Oil Pan Included

No

Timing Cover Included

Nο

Harmonic Balancer Included

No

Engine Displacement

220.0CID

Main Bearing Cap Bolt Quantity

2

Engine Block Material

Aluminum

Flexplate Included

No

Engine Water Pump Included

No

Valve Covers Included

Νo

Windage Tray Included


nuli

How It Works:

The engine supplies the necessary torque and horsepower that is needed to propel the vehicle down the road. The most popular engines are gasoline and diesel, however some are set up to run on propane or natural gas.

When it Doesn't Work:

Failure can take place for a variety of reasons. Always follow the recommended maintenance schedule to prolong the life of



Line: PTQ Item: DDHH

Product Attributes

Product Attributes	
Warranty: All Others	5015.57 Cost \$5119.00
New Or Remanufactured: Remanufactured	2013.
Number Of Cylinders: 6	- Kallaga
Fuel Type: Gasoline	
Engine Size (L): 3.6 Liter	core #820.00
Engine Size (CI): 220 Cubic Inch	core 188210.
Block Material: Aluminum	(O'Reilly)
Head Type: DOHC	() Rollin's
Head Material: Aluminum	+ Shipping
Carburetor Included: No	+ SNIV >
Throttle Body Included: No	
Exhaust Manifold Included: No	
Intake Manifold Included: No	
Ignition Control Module Included: No	
Spark Plug Wires Included: No	
Spark Plugs Included: No	
Thermostat Included: No	
Timing Belt Included: No	1 1 0(1)
Timing Chain Included: Yes	(1) (05)
Water Pump Included: No	trum on constant
Oil Pan Included: No	14293,67 cost / Mutozone
Oll Dipstick Tube Included: No	40000
Timing Cover Included: Yes	+ shipping
Valve Cover Included: No	
Wiring Harness Included: No	
and the second s	

Brand Details

Power Torque engines are built to meet or exceed OE fit, form, and function. Each engine is complete and drop-in ready as a direct replacement for simple installation without the need for modification. Power Torque Engines are assembled with high-quality components to ensure peak

Staff Report

April 24, 2025

To: Board of Aldermen

From: Happy Welch Re: Sewer Backup



Issue:

Alderman Raney requested that Mike James, 770 Point Basse Dr., get a chance to discuss his sewer backup costs from the April 4/5 rains and a request for reimbursement.

We can submit his claim (and others) to insurance but in the past I have seen them rejected due to the nature of the heavy rains and not due to a lack of maintenance and negligence on the city's part. Mr. James may then ask for reimbursement out of city funds.

When a resident has a sewer backup we offer a free backflow preventer they can have installed by a licensed plumber that will protect them from rain swollen sewer mains issues.

Recommendation:

We will submit his claim to insurance and wait for their determination but if rejected the city should not reimburse.